

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF STATE LANDS & FORESTRY  
3 TRIAD CENTER, SUITE 400  
355 WEST NORTH TEMPLE  
SALT LAKE CITY, UTAH 84180-1204

May 2, 1986

Urango Mining Co., Inc.  
c/o Banqwest Resources Limited  
650 - 409 Granville Street  
Vancouver, B.C., Canada V6C 1T2

Gentlemen:

RE: Utah State Metalliferous Minerals Lease ML 25282

I recently made a visit to lands covered by the above numbered lease and found the premises in an unsatisfactory condition. Fences around shafts were down and there are many uncovered vent/drill holes.

Fences around the shafts need to be repaired, unnecessary vent/drill holes need to be plugged, and the others need to be covered temporarily. There is also some broken down machinery and debris that will need to be removed upon final cessation of operations.

You should try to make regular inspections of the site to insure the mine site is kept in a safe condition.

If you have any questions concerning this matter, please contact me.

Sincerely,

JERRY W. MANSFIELD  
MINERAL RESOURCES SPECIALIST

JWM/eb

cc: Dave Wham  
Division of Oil, Gas, & Mining